

Office Phone: 401-729-5013

401-729-5019

Fax Number: 401-727-3423 Email: jdavies@pwsb.org Web Page: www.pwsb.org

## PAWTUCKET WATER SUPPLY BOARD Cross-Connection Control & Backflow Prevention Certified Tester Requirements

Pawtucket Water Supply Board (PWSB) ONLY accepts backflow test results from Certified Backflow Testers who have registered with our utility. If you are a new backflow tester, certified through ABPA, NEWWA, TREO or the USC method and you would like to submit your Backflow Test Maintenance results for assemblies tested in the PWSB system which includes Pawtucket, Central Falls and the Valley Falls section of Cumberland (Marshall Avenue-South) then here is what you MUST provide to us.

- 1) A copy of your driving license, tester/inspector certification card showing certification number and expiration date.
  - (DUE EVERY 3YRS)
- 2) The manufacturer's test kit calibration certificate for your test kit. (DUE ANNUALLY)
- 3) Copy of Liability Insurance with expiration date. (DUE ANNUALLY)

Also provide mailing address, contact number, fax number, and an email address and return it along with the Backflow Questioner which can be found on our website at the above address.

Once we receive all your Certified Backflow Tester information only then will your name appear on our list of certified testers which will also be published on our website (updated approximately every 4 months).

## **PLEASE NOTE:**

It is the responsibility of the Certified Tester to re submit all certificates and insurance to the above address within 30 days of expiration dates to remain on the PWSB testers list.

Backflow testing is required for all new installations and annually thereafter.